

TYRE INSPECTION REPORT

 Company: THIESS/EASTERN TRACTORS

 Site: MT THORLEY


 Inspection date : 4/11/2021

 Veh. Make & type: CAT789B

 Fleet : RD1014


Hours : _____

Position	Size	Brand	Tread Spec	Serial Number	Original Tread (mm)	Remaining Tread (mm)	Tyre Condition	Rim / Wheel Number	Tyre Change Priority	Comments
1	42/90R57	B/S	VRDPY	S8K000210		71/70	A	T57-0974		OK
2	42/90R57	B/S	VRDPY	S8J005416		75/70	A	T57-0976		OK
3	42/90R57	B/S	VRDPY	S9S003123		61/58	FAIR B	T57-0947		OK
4	42/90R57	B/S	VRDPY	S9R005736		59/60	FAIR B	CNR		OK
5	42/90R57	B/S	VRDPY	S7B005524		60/60	C POOR	CNR		SIDEWALL CUTS AND DAMAGE
6	42/90R57	B/S	VRPS	S7B005333		45/48	C POOR	T57-1162		SIDEWALL CUTS AND DAMAGE




TYRE CONDITION	
A	GOOD
B	FAIR
C	POOR

Tyre Change Priority	
Urgent	ASAP
Priority 1	Within 1 month
Priority 2	Within 2 months



Notes :

POS 1/2 TYRES OK
POS 5/6 THE WORST WITH SIDEWALL DAMAGE ON BOTH INSIDES OF TYRES
WITH POS 6 SIDEWALL CUTS TO OUTSIDE



POSITION 1



POSITION 2



POSITION 3/4



POSITION 5/6



POS 6 SIDEWALL DAMAGE

