



Model	Component Description	Service Type	Est Life	Scheduling Method	Act Comp C/O Hrs	Act Comp C/O Date	Current Hrs on Comp	Current Days on Component	% Life Remaining	Comment
777F	BEARING, A-FRAME	C	20000	SMU	35,290	1/11/2017	10,668	1070	47%	Replaced at tank c/out.
777F	BEARING, WHEEL, FRONT LEFT	C	14000	SMU	35,290	1/11/2017	10,668	1070	24%	Replaced at shutdown.
777F	BEARING, WHEEL, FRONT RIGHT	C	14000	SMU	35,290	1/11/2017	10,668	1070	24%	Replaced at shutdown.
777F	BRAKE GP, FRONT LEFT	C	14000	SMU	35,290	1/11/2017	10,668	1070	24%	Overhauled by Birrana due to Hyd system contamination.
777F	BRAKE GP, FRONT RIGHT	C	14000	SMU	35,290	1/11/2017	10,668	1070	24%	Overhauled by Birrana due to Hyd system contamination.
777F	BRAKE GP, REAR LEFT	C	20000	SMU	35,290	1/11/2017	10,668	1070	47%	Overhauled by Birrana due to Hyd system contamination.
777F	BRAKE GP, REAR RIGHT	C	20000	SMU	35,290	1/11/2017	10,668	1070	47%	Overhauled by Birrana due to Hyd system contamination.
777F	CYLINDER, STEERING, LEFT	C	14000	SMU	35,290	1/11/2017	10,668	1070	24%	Repair and return.
777F	CYLINDER, STEERING, RIGHT	C	14000	SMU	44,219	7/02/2020	1,739	242	88%	leaking oil. [off=????] [ON= 1-5031]
777F	CYLINDER, SUSPENSION, FRONT LEFT	C	20000	SMU	42,739	12/10/2019	3,219	360	84%	Collapsed - pieces broken out of chrome. [OFF= Not Available] [ON=K015870]
777F	CYLINDER, SUSPENSION, FRONT RIGHT	C	20000	SMU	20,497	10/01/2014	25,461	2461	-27%	C/O on hours
777F	CYLINDER, SUSPENSION, REAR LEFT	C	5000	SMU	33,146	9/07/2017	12,812	1185	-156%	LEAKING. [OFF=1913] [ON=0020]
777F	CYLINDER, SUSPENSION, REAR RIGHT	C	5000	SMU	33,146	9/07/2017	12,812	1185	-156%	LEAKING. [OFF=1912] [ON=0267]
777F	DIFFERENTIAL	C	14000	SMU	33,715	4/02/2017	12,243	1340	13%	AXLE SNAPPED FAILING R/H OF DIFF. [OFF= LSP01271] ON = Y33397
777F	ENGINE	C	18000	SMU	34,210	18/03/2017	11,748	1298	35%	Failed (broken connecting rod) - Serial on LJW5494
777F	FINAL DRIVE, LEFT	C	20000	SMU	35,284	24/07/2017	10,674	1170	47%	BRAKE PACK FAILURE - S/N 21-2
777F	FINAL DRIVE, RIGHT	C	20000	SMU	34,302	17/04/2017	11,656	1268	42%	BRAKE PACK FAILURE
777F	PUMP, HOIST	C	14000	SMU	35,288	2/08/2017	10,670	1161	24%	PUMP FAILURE. OFF=K0216-00235. ON=SERIAL No. NOT LEGIBLE
777F	PUMP, STEERING	C	14000	SMU	35,290	1/11/2017	10,668	1070	24%	C/out on hours.
777F	PUMP, T/C & BRAKE	C	14000	SMU	35,290	1/11/2017	10,668	1070	24%	C/out on hours.
777F	PUMP, TRANSMISSION OIL	C	14000	SMU	35,290	1/11/2017	10,668	1070	24%	C/out on hours.
777F	RADIATOR	C	18000	SMU	34,210	21/03/2017	11,748	1295	35%	C/O WITH ENGINE ON W/O 60421
777F	ROTOCHAMBER, FRONT	C	20000	SMU	35,290	1/11/2017	10,668	1070	47%	C/out on hours.
777F	ROTOCHAMBER, REAR	C	14000	SMU	35,290	1/11/2017	10,668	1070	24%	C/out on hours.
777F	SEAT	C	6000	SMU	43,375	29/11/2019	2,583	312	57%	C/O SEAT OPERATOR COMPLAINT - UP ON HOURS
777F	SLACK ADJUSTER, FRONT	C	14000	SMU	35,290	1/11/2017	10,668	1070	24%	C/out on hours.
777F	SLACK ADJUSTER, REAR	C	14000	SMU	35,290	1/11/2017	10,668	1070	24%	C/out on hours.
777F	TORQUE CONVERTER	C	14000	SMU	35,290	1/11/2017	10,668	1070	24%	C/out on hours.
777F	TRANSMISSION	C	14000	SMU	35,290	1/11/2017	10,668	1070	24%	C/out on hours.
777F	TURBO, LEFT	C	18000	SMU	34,210	18/03/2017	11,748	1298	35%	C/O WITH ENGINE
777F	TURBO, RIGHT	C	18000	SMU	23,893	9/11/2014	22,065	2158	-23%	Failed
777F	UNI JOINTS	C	14000	SMU	35,290	1/11/2017	10,668	1070	24%	C/out on hours.