



Position Modifier Code	Activity Description	Comment	Replacement Total Frame Hours	Replacement Date	Current Component Hours
	BLADE PINS & BUSHES		41,737	Jan-23	13,603
CTR	EQUALISER BAR		52,426	Apr-25	2,914
	PIVOT SHAFT		41,738	Jan-23	13,602
RHS	TRACK FRAME		51,426	May-25	3,914
LHS	TRACK FRAME		51,426	May-25	3,914
RHS	TRACK ROLLER GROUP		51,426	May-25	3,914
LHS	TRACK ROLLER GROUP		51,426	May-25	3,914
RHS	TRACK PIN & BUSH TURN	Next activity is track replacement	47,780	Jun-24	7,560
	ENGINE MIDLIFE	Updated to match theoretical ne	50,163	Nov-24	5,177
LHS	TRACK PIN & BUSH TURN	Next activity is track replacement	47,780	Jun-24	7,560
LHS	TRACK	Matched to condition and line up	39,665	Jul-22	15,675
RHS	STEERING CLUTCH & BRAKE		50,551	Dec-24	4,789
LHS	STEERING CLUTCH & BRAKE		54,167	Sep-25	1,173
RHS	FINAL DRIVE		41,738	Jan-23	13,602
LHS	FINAL DRIVE		41,738	Jan-23	13,602
	TRANSMISSION		41,738	Jan-23	13,602
	TORQUE CONVERTER		54,167	Sep-25	1,173
RHS	RIPPER TILT CYLINDER		39,665	Jul-22	15,675
RHS	TRACK	Matched to condition and line up	39,665	Jul-22	15,675
	ENGINE		41,738	Jan-23	13,602
	HYDRAULIC CONTROL VALVE		41,738	Jan-23	13,602
	HYDRAULIC COOLER FAN MOTOR		46,215	Feb-24	9,125
	HYDRAULIC COOLER FAN PUMP		46,215	Feb-24	9,125
LHS	RIPPER TILT CYLINDER		39,665	Jul-22	15,675
RHS	RIPPER LIFT CYLINDER		39,665	Jul-22	15,675
RHS	BLADE TILT CYLINDER		41,738	Jan-23	13,602
LHS	BLADE TILT CYLINDER		41,738	Jan-23	13,602
RHS	BLADE LIFT CYLINDER		41,738	Jan-23	13,602
LHS	BLADE LIFT CYLINDER		50,551	Dec-24	4,789
	IMPLEMENT PUMP		50,163	Nov-24	5,177
	RADIATOR		41,738	Jan-23	13,602
	BLADE REPAIRS		41,737	Jan-23	13,603
LHS	RIPPER LIFT CYLINDER		39,665	Jul-22	15,675
	TRANSMISSION OIL PUMP		47,283	May-24	8,057